

Originator : KEVIN MILLER Schedule Date :  
Planner : KEVIN MILLER Priority : 3C  
Drawing No : 1TGA-M2079 Clearance : NO  
Equip No/Cat: 1TGA--1A 1 Tag Request :  
Project ID : Text ID :  
Shutdown : N No Shutdown Frequency : NOT SCHEDULED  
Ref No : Last Reading : No Reading

Date Completed: \_\_\_\_\_ Failure Code: \_\_\_\_\_  
Completed By : \_\_\_\_\_ Signature : \_\_\_\_\_  
Accepted By : \_\_\_\_\_ Signature : \_\_\_\_\_

**\*\* Delay Codes Legend \*\***

W=Whse C=CrSp T=Tag TL=Tool P=Plan  
**\*\* Record Time Daily \*\***  
Delays  
Code/Hrs

Step	Job Scope	MN	DY	Safety and Additional Information
1	TIME EXPENDED TO DISCONNECTO TURBINE OUTAGE OFFICE TRAILERS AND ASSEMBLE TRANSFORMERS ON CART.  =====	2	1	***** SAFETY / ENVIRONMENTAL REQUIREMENTS: A. ALWAYS WEAR THE REQUIRED PPE.  B. NO WORK CARD. CORD IS PLUGGED INTO A WELDING OUTLET.  ***** ADDITIONAL INFORMATION: A. OBTAIN NEW CART STAGED.
=====				
BARRY EGGLESTON IS FAMILIAR WITH THIS JOB. =====				
***** JOB SCOPE: 1. DISCONNECT BOTH TRAILERS. REMOVE THE PERMANENT TRANSFORMER ON OUR OLD TRAILER, AND ASSEMBLE BOTH AND PREWIRE ON CART.  2. SEE KEVIN FOR PAPERWORK TO PLACE IN TOOL ROOM.				

**\*\* IMPORTANT NOTICE \*\***  
YOU ARE RESPONSIBLE FOR YOUR OWN SAFETY AND MUST  
ENSURE THAT THE REQUIRED PPE IS WORN FOR EVERY  
JOB YOU ARE DOING. IF YOU HAVE ANY QUESTIONS  
CONCERNING THE WORK RULES, SAFETY CODES, OR  
REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR.

-----  
Job Feedback/Historical Notes:



01-19846-7

IP7\_005510

CREW: 62

WORK ORDER TYPE: PM REPAIR

01-19846-7

ISSUE DATE 01/06/11

Page 2 Of 2

## \*\* Work Order Parts List \*\*

Part No	Description	PO/Req/SIR	Date Due	U/M	Reqd	Commit	Issued/Rcvd
1	50237	S 214932	05/09/02	FT	170	0	170
2	DIRECT	02-23763	03/29/02	EA	1	0	1

IP7\_005511